

Oil Field Environmental Incident Summary

Incident: 20140131073119

Date/Time of Notice: 01/31/2014 06:55

Responsible Party: PumpCo Energy Services

Well Operator: EOG RESOURCES, INC.

Well Name: Wayzetta 28, 29 & 38-1424H

Field Name: PARSHALL

Well File #: 25747

Date Incident: 1/31/2014

Time Incident: 02:45

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 90

Sec: 14

Qtr: NE NE

Location Description:

Submitted By: Keith Kallberg

Received By:

Contact Person: Jason Rhines
3305 4th Ave NW
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	50	barrels	0	barrels	50	barrels
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/4/2016

Clean Up Concluded: 1/31/2014

Risk Evaluation:

N/A

Areal Extent:

100 ft. x 100 ft. on location

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Frac operation was shut down & a vac truck was contacted to remove the free fluids, PumpCo hands will assist with cleanup. Amount of fluid recovered is unknown at this time.

Wastes Disposal Location: 3rd party disposal facility

Agencies Involved:

Updates

Date: 2/4/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from an on-location valve or piping leak remained on location, according to the report. NDIC retains oversight.